



# GOLDCORP – AUTOCLAVE SS ENCLOSURE





**PROBLEM:** Autoclave environment affected valve life & operation



**SOLUTION:** We packaged a MAC valve bank of 6 on a special manifold with individual inlets into a stainless steel enclosure.

*'Plug & Play'*



## Stainless Steel Enclosure installed in 2007




*This is a current 2011 installation picture*



**SKEANS**

*Current 2011 picture of inside the same  
Stainless Steel Enclosure (4 yrs later)*





## Testimonial from Goldcorp

*“No breakdowns to date since installation in 2007”*

*“In the past, we would destroy 2 to 3 solenoids per year with associated Autoclave down time”*

*“Self bleeding air supply isolation valves simplify lockout”*

*“Wiring has been kept clean and neat”*

*“Discharge valves react quicker than before, which has helped to increase service life”*

*“Overall - a good quality installation, easy to maintain”*