

Optical Distance Sensor



Customer Pain:

The client came to us looking to replace their older optical distance sensors, due to errors causing production disruptions. These older sensors were unable to see through the dust and debris that would collect over the sensors. Due to the nature of their business, they were unable to find a cleaner solution to this issue and cleaning the sensors was dangerous for their employees.

Solution:

After some deliberation with the client, we decided that a Leuze optical distance sensor would be the best solution for their issue. With their new technology, these sensors saw straight through the dust and debris that would build upon the equipment.

Results:

Most importantly, the client no longer needed to risk employee safety cleaning the hazardous equipment. Therefore, our solution helped the client build a safer and more secure work environment for their employees. Additionally, eliminating this downtime meant that production became continuous. Greatly improving the amount of product produced.

Coquitlam

604.777.4247
sales@skeans.com

Kamloops

250.828.2344
sekam@skeans.com

Prince George

250.564.2201
sepg@skeans.com

Edmonton

780.463.8400
seal@skeans.com

Calgary

403.279.6644
secal@skeans.com

Saskatoon

306.651.3366
sesk@skeans.com

Winnipeg

204.633.9699
sewin@skeans.com